

KENWOOD

SB-944

SUBJECT TH-205/215/415 VOLUME/SQUELCH CONTROL IMPROVEMENT	DATE 10/28/88
<p>The transceivers mentioned above can be mechanically improved by adding a bracket assembly to the volume and squelch controls. The bracket assembly is being used in current production and is available for older units from the Kenwood Parts Department.</p> <p>BRACKET ASS'Y W05-0235-00</p> <ol style="list-style-type: none">1. Disconnect the battery pack and antenna.2. Remove the 7 screws from the back panel of the transceiver (Figure 1).3. Lift the front panel from the transceiver and lay it to the right side.4. Disconnect the 2 flex cables and remove the 3 screws from the IF unit (Figure 2).5. Pull the top panel off and then remove the IF unit.6. Remove the knobs and black cloth from the volume and squelch controls.7. Inspect the controls to insure they are mounted flush to the board. If they are not flush, completely desolder and resolder the controls.8. Insert the bracket over the controls and tighten the nuts (tighten the nut on the volume control first). See Figure 3 for the bracket assembly view.9. Assemble the transceiver by reversing steps 1 - 6.	
<p>This modification may be covered under warranty. Time required for this modification is 0.5 hrs or less. (C) 91088TKC</p>	

KENWOOD U.S.A. CORPORATION

2201 EAST DOMINGUEZ STREET - LONG BEACH, CALIFORNIA 90810
MAILING: P.O. BOX 22745 - LONG BEACH, CALIFORNIA 90801-5745
TELEPHONE: (213) 639-9000




FIGURE 1




FIGURE 2

